





# SOLAR PANEL MC4 CONNECTOR WIRING

## MC4 CONNECTOR ASSEMBLY



### 1. CRIMP MALE CONNECTOR TO CABLE



### 2. INSTALL NUT ON CABLE



### 3. INSERT CABLE INTO FITTING



### 4. INSTALL RUBBER WASHER & TIGHTEN NUT

